



Wednesday, April 20, 2016

**Notice: Cessation of Support & Repairs on Systems Controllers**

Due to increasing issues relating to parts obsolescence, MMR Technologies, Inc. no longer has the capability to perform repairs on the SB100 Seebeck Effect Measurement System Controller & the K20 Temperature controller.

This is effective immediately. Any repair attempts after this date will be on a 'best efforts' basis without guarantee of success.

The H50 Hall Effect Measurement System Controller will be supported until Dec 31<sup>st</sup> 2017.

The next generation controllers replacing the SB100, K20 & H50 are the SB1000, K2000 & H5000 respectively.

Please contact [sales@mmr-tech.com](mailto:sales@mmr-tech.com) for more information.

*Andrew S. Boyle*

*Chief Operating Officer*

*MMR Technologies, Inc.*

41 Daggett Drive, San Jose, CA 95134

Phone: +1 (650) 962 9620

Fax: +1 (650) 962-9647 Email: [info@mmr-tech.com](mailto:info@mmr-tech.com)

Web: [www.mmr-tech.com](http://www.mmr-tech.com)

[www.mmr-tech.com](http://www.mmr-tech.com)